



Robert Bosch
Car Multimedia GmbH
Postfach
31132 Hildesheim
Visitor:
Robert-Bosch-Straße 200
31139 Hildesheim
Tel +49 5121 49-0
www.bosch.com

DECLARATION OF CONFORMITY

2021-09-17

In accordance with UK Government guidance.

We declare under our sole responsibility that our product,

Model Name	Audi FPK Gen1
Type of device	
Instrument cluster	
Features	
Display, Immobilizer, CAN, MOST	
Other accessories	
-	
Hardware version	
H12, H14, H15, H16, H17, H18, H19, H20, H33, H34, H35, H36, H37, H39, H40, H42, H43, H44, H45, H46, H21	
Software version	
0224, 0268, 0296, 0325, 0326, 0358, 0359, 0109, 0140; 0142; 0145; 0146; 0147; 0047, 0066, 0068, 0107, 0108, 0069, X159; 0160; 0161; 0162, 0382; 0383; 0384; 0385; 0386, 0204; 0205; 0207, 0111, 0402, 0234, 0235; 0113; 0112; 0208; 0360; 0387; 0149; 0163; 0327; 0403; 0070	

Part numbers			
Bosch part number	Audi part number	Bosch part number	Audi part number
0 263 714 002	8S0 920 790	0 263 742 059	8V0 920 794A
0 263 714 004	8S0 920 890	0 263 742 060	8V0 920 890A
0 263 714 015	8S0 920 790A	0 263 742 061	8V0 920 894A
0 263 714 016	8S0 920 890A	0 263 742 072	8V0 920 790B
0 263 714 019	8S0 920 790B	0 263 742 073	8V0 920 794B
0 263 714 020	8S0 920 890B	0 263 742 074	8V0 920 890B
0 263 714 025	8S0 920 790C	0 263 742 075	8V0 920 894B
0 263 714 026	8S0 920 890C	0 263 742 077	8V0 920 890C
0 263 714 031	8S0 920 790D	0 263 742 078	8V0 920 894C
0 263 714 032	8S0 920 890D	0 263 742 082	81A 920 795 A
0 263 714 033	8S0 920 890E	0 263 714 036	8S0 920 790 F
0 263 742 079	8V0 920 790 C	0 263 714 037	8S0 920 890 F
0 263 742 076	81A 920 795	0 263 742 081	81A 920 790
0 263 742 041	8V0 920 790	0 263 742 088	8V0 920 798
0 263 742 042	8V0 920 794	0 263 714 042	8S0 920 790 G
0 263 742 043	8V0 920 890	0 263 714 043	8S0 920 890 G
0 263 714 044	8S0 920 790 H	0 263 742 086	81A 920 790 A
0 263 742 044	8V0 920 894	0 263 742 087	81A 920 795 B
0 263 742 058	8V0 920 790A	0 263 742 089	81A 920 790 B
0 263 714 045	8S0 920 790 J	0 263 742 090	81A 920 790 C

is in conformity with the relevant UK Statutory Requirements (and their amendments):

The Radio Equipment Regulations 2017 (SI 2017/1206).

The following designated standards were applied when carrying out the conformity assessment:

Standard	Title	Regulation
EN 62368-1: 2014 + AC: 2015 + A11: 2017	Audio/video, information and communication technology equipment Part 1: Safety – Requirements Report: 1-7540_18-01-03 Report: G0M-1409-4198-SEO001X-V01	6 (1) (a)



Standard	Title	Regulation
EN 50665: 2017	Generic standard for assessment of electronic and electrical equipment related to human exposure restrictions for electromagnetic fields (0 Hz - 300 GHz) Report: G0M-1511-5241-TEU311EX-V01	6 (1) (a)
EN 301 489-1 V2.2.0	Electromagnetic compatibility and Radio spectrum Matters (ERM); Electromagnetic Compatibility (EMC) standard for radio equipment and services; Part 1: Common technical requirements Report: G0M-1409-4198-EE01RE-V01	6 (1) (b)
EN 301 489-3 V2.1.1 (Final Draft)	Electro-magnetic compatibility and Radio spectrum Matters (ERM); Electromagnetic Compatibility (EMC) standard for radio equipment and services — Part 3: Specific conditions for Short- Range Devices (SRD) operating on frequencies between 9 kHz and 246 GHz Report: G0M-1409-4198-EE01RE-V01 Report: TB141_CE EMC 0	6 (1) (b)
EN 300 330 V2.1.1	Short Range Devices (SRD); Radio equipment in the frequency range 9 kHz to 25 MHz and inductive loop systems in the frequency range 9 kHz to 30 MHz Report: G0M-1511-5241-TEU330RI H35-V01 Report: G0M-1511-5241-TEU330RI H36-V01	6 (2)

Assessment	Assesment_CE_Audi_FPK_Gen1_2015_12_21_V1 Assessment_Audi_FPK_Gen1_2016_03_18_U Audi_FPK_Gen1_Assessment_2017_03_30_s Assessment_Audi_FPK_Gen1_2017_05_29 Riskassessment_Audi_FPK_Gen1_2018_02_01 Riskassessment_Audi_FPK_Gen1_2018_02_13 Riskassessment_Audi_FPK_Gen1_2018_11_19 Riskassessment_Audi_FPK_Gen1_2018_12_06 Riskassessment_Audi_FPK_Gen1_2019_03_11 Riskassessment_Audi_FPK_Gen1_2019_04_05 Riskassessment_Audi_FPK_Gen1_2019_05_06 Riskassessment_Audi_FPK_Gen1_2019_08_05 Riskassessment_Audi_FPK_Gen1_2019_08_07 Riskassessment_Audi_FPK_Gen1_2019_11_21 Riskassessment_Audi_FPK_Gen1_2019_12_06 Riskassessment_Audi_FPK_Gen1_2019_12_12 Riskassessment_Audi_FPK_Gen1_2020_01_14 Riskassessment_Audi_FPK_Gen1_2020_01_14_2 Riskassessment_Audi_FPK_Gen1_2020_03_16 Riskassessment_Audi_FPK_Gen1_2020_03_20 Riskassessment_Audi_FPK_Gen1_2020_5_5 Riskassessment_Audi_FPK_Gen1_2020_6_9_3E10035497 Riskassessment_Audi_FPK_Gen1_2020_6_9_3E10035491 Riskassessment_Audi_FPK_Gen1_2020_7_1
-------------------	---



2021-09-17

Page 4 of 4

	Riskassessment_Audi_FPK_Gen1_2020_7_8 Riskassessment_Audi_FPK_Gen1_2020_7_9 Riskassessment_Audi_FPK_Gen1_2020_8_6 Riskassessment_Audi_FPK_Gen1_2020_8_6_02 Riskassessment_Audi_FPK_Gen1_2020_10_29 Riskassessment_Audi_FPK_Gen1_2020_10_29_2 Riskassessment_Audi_FPK_Gen1_2020_10_14 Riskassessment_Audi_FPK_Gen1_2020_11_10 Riskassessment_Audi_FPK_Gen1_2021_2_2 Riskassessment_Audi_FPK_Gen1_2021_3_10 Riskassessment_Audi_FPK_Gen1_2021_3_11 Riskassessment_Audi_FPK_Gen1_2021_04_13 UK_RA_AUDI_FPK_Gen1_2021_06_04 RA_AUDI_FPK_GEN1_2021_06_10 Riskassessment_Audi_FPK_Gen1_2021_09_06
--	--

HILDESHEIM

Author:
XC/QMM-VR2-S
Dg

i.V.

Stefan Lemke
Vice President Quality Management